

APPENDIX E
PIEZOMETER STATUS SUMMARY

APPENDIX E
PIEZOMETER STATUS SUMMARY
Recorded April 1, 2019

Well ID number	Status	Well ID number	Status
B120	Secure, no repairs needed	B490	Secure, no repairs needed
B121	Secure, no repairs needed	Bulb 1	Secure, no repairs needed
B128	Secure, no repairs needed	Bulb 2	Secure, no repairs needed
B128 Deep	One bolt replaced, well secure	CCC1	Secure, no repairs needed
B150	Secure, no repairs needed	CCC2	Secure, no repairs needed
B158	Secure, no repairs needed ⁽¹⁾	CCC3	Secure, no repairs needed
B163	Secure, no repairs needed	CCCT	Secure, no repairs needed ⁽¹⁾
B175S	Secure, no repairs needed ⁽¹⁾	CTP	Secure, no repairs needed ⁽¹⁾
B175W	Secure, no repairs needed	CTP Deep	One bolt replaced, well secure ⁽¹⁾
B177	Secure, no repairs needed	CTPS	Secure, no repairs needed
B178	Secure, no repairs needed	DHR	Secure, no repairs needed
B180	Secure, no repairs needed ⁽¹⁾	EERC	Secure, no repairs needed
B185	Secure, no repairs needed ⁽¹⁾	EPA	Secure, no repairs needed
B194	Secure, no repairs needed	ETA	Secure, no repairs needed
B195	Secure, no repairs needed ⁽¹⁾	ETA01	Secure, no repairs needed
B197	Secure, no repairs needed	ETA02	Secure, no repairs needed
B277	Secure, no repairs needed	ETA03	Secure, no repairs needed
B278	Secure, no repairs needed	FG	Secure, no repairs needed
B280A	Well box broken, cap does not fit under cover Additional repair required ⁽²⁾	GEO	Secure, no repairs needed
B280B	Additional repair required	MFA	Secure, no repairs needed
B300	Secure, no repairs needed	NRLF	Secure, no repairs needed
B38	Secure, no repairs needed ⁽¹⁾	PZ11	Secure, no repairs needed
B38 Deep	Secure, no repairs needed	PZ8	Well box broken, well cap not watertight Additional repairs required ⁽³⁾
B450	Secure, no repairs needed	PZ9	Secure, no repairs needed
B460	Secure, no repairs needed	RWF	Secure, no repairs needed ⁽¹⁾
B473	Secure, no repairs needed	TP1	Secure, no repairs needed
B474	Secure, no repairs needed	TP2	Secure, no repairs needed
B480	Secure, no repairs needed	WSM01	Secure, no repairs needed
B480 Deep	Secure, no repairs needed	WTA	Secure, no repairs needed

Notes

1. Contained water within the well box. The water was removed and each cap identified as water tight. No repairs were required.
2. Well box will be repaired in November 2019
3. Well box and PVC piezometer casing will be repaired in November 2019